

RedShift Laser Parameter Tuning Checklist

Pre-Cut Inspection

- Lens is clean and free of debris
- Mirrors are aligned properly
- Focus is set correctly for material thickness
- Assist gas pressure is verified
- Nozzle is clean and undamaged
- Material is flat and secured
- Exhaust ventilation is on

Test Cut Procedure

- Use scrap material from same batch
- Start with "Optimal" speed (not "Max")
- Cut simple test shapes:
 - 50mm straight line
 - 20mm square
 - 20mm diameter circle
- Inspect results for:
 - Complete cut-through
 - Edge quality (smoothness, no charring)
 - Kerf width consistency
 - Dross on bottom

Parameter Adjustment

If cut doesn't go through:

- Reduce speed by 10%
- Re-test
- If still not through, reduce another 10% or increase power 5%

If cut is burned or too wide:

- Increase speed by 10%
- OR reduce power by 5%
- Re-test

Important: Only change ONE parameter at a time!

Results Recording

Record in your parameter library:

- Material type and supplier
- Thickness (measured)
- Power setting (%)
- Speed (mm/s)
- Focus position
- Gas type and pressure
- Result rating (1-5)
- Notes/observations
- Date tested

Troubleshooting Quick Reference

Problem	Likely Cause	Solution
Top cuts, bottom doesn't	Focus too high	Lower focus to mid-thickness
Burning/charring	Too much power / too slow	Reduce power or increase speed
Incomplete cut	Not enough power / too fast	Increase power or reduce speed
Tapered kerf	Focus wrong	Adjust focus position
Dross on bottom	Insufficient gas flow	Increase assist gas pressure